





T3 OPERATOR'S GUIDE

Machine/Tool Protection

The primary function of this monitor is to reliably measure speed and force.

SETTING & CLEARING COUNT (123 BUTTON)



Press the **123 Button**  to bring up the count view/adjustment display.


Press the number you wish to modify. Using the keypad, type in the desired number and press “E” to confirm the changes.

Entering “0” in the Count field will maintain the count but won’t shut the machine off.

Count can both be set and cleared, while Made can only be cleared.

Press “Set” to disable the keyboard.

SETTING LIMITS (CURVE BUTTON)



Press the **Curve Button**  to activate the channel adjustment display.

Press the number below **LL** or **HL**, and it will begin to flash. Using the keypad, input the desired number for this limit. Press “E” to modify the **HL** Limit. Press “E” to confirm the changes.

In Auto Limit Mode, the “Set” tab will appear in red. Limits will be set by the monitor.

To leave the set Limits option, press “Set.”

Limits set at 000 AVG 999 will have no control.

NO-FEED (CURVE BUTTON)

Thread Rollers Only



To find the no-feed limit, run the roller with parts and hold them back in the rail to simulate a no-feed. With parts, the average is 498; holding them can gives an average of 4. Set the no-feed limit to 8; if it drops below 8, the die area is empty.

Select the **No-Feed Button**, and the **AVG** will switch to the No-Feed Limit setting. Then, using the keypad, type in the desired number and press “E” to confirm the changes.



T3 OPERATOR'S GUIDE

MODEL

This monitor has two input types. The first connects to the Force Sensor, a device that gives a precise analog signal based on the applied force, enabling real-time monitoring within defined limits. The second input is from the Cam Sensor, which acts like a trigger to determine the position of the ram on the machine. The placement of these sensors is important for the functioning of the monitor, as it ensures safety by stopping the machine if the force exceeds the set limits to prevent further damage or faulty parts.

MORNING CHECKLIST

PLEASE ANSWER ALL QUESTIONS

CIRCLE ONE

Does the monitor turn on? _____ **YES / NO**

Is the monitor accurately counting? _____ **YES / NO**


Does the monitor maintain an average limit of around 500? _____ **YES / NO**

Does the monitor power off the machine when an error occurs? _____ **YES / NO**


Do you have any questions how the monitor works? _____ **YES / NO**

If you answer **NO** to any questions, contact maintenance or consult your ACI technician.

OVERVIEW



ERRORS (CURVE BUTTON)



When the **AVG** number falls below the **LL** or rises above the **HL** limits at any station, the machine will stop, and the status will indicate which channel has gone beyond the limit.

To return the monitor to **Test Mode**, press the **RESET Button**.